


LOCATION MAPS



COUNTY OF SAN BERNARDINO
DEPARTMENT OF PUBLIC WORKS
DISTRICT 2
YARD 1
H15037



LOCATION MAP
MOUNTAIN AVENUE AND OTHER ROADS
Various Roads/Locations
Rehabilitation, ADA Ramps Update



COUNTY OF SAN BERNARDINO
 DEPARTMENT OF PUBLIC WORKS
DISTRICT 2
YARD 1
H15037



LOCATION MAP
MOUNTAIN AVENUE GUARDRAIL REPLACEMENT
 Various Roads/Locations
 Guardrail Replacement

CROSS GUTTER AND AC DIKE PHOTOS



Figure 1. Damaged Existing Cross Gutter in 24th Street and Burt Street.



Figure 2. Damaged Existing Cross Gutter in 24th Street and Burt Street.



Figure 3. Existing AC dike at 2525 Mountain Drive.




Figure 4. Existing AC dike at 2525 Mountain Drive.